

PA/UIC INSPECTION REPORT

1A(02)

Inspection Type NPI Inventory No. DS2418  
 Inspection Frequency status Authorization \_\_\_\_\_  
 Violation Code \_\_\_\_\_ Authorized to Inject \_\_\_\_\_

Company/Operator KWB Oil Properties Management Co  
 Business Address 15 East 5th St #3300 Tulsa, OK 74103  
 Individual Contacted Ted Pope Title \_\_\_\_\_  
 Lease Name & Well No. #29

Legal Description (b) (9)

Well Information: SWD/ER, Active/TA/P&A  
 Authorized Injection: Pressure \_\_\_\_\_ Rate \_\_\_\_\_  
 Long String Casing Size 5.5" Tubing Size 2.38"

Report of Conditions as of this Date:

Lease: Active/Inactive Well hooked up for injection: Yes/No  
 Injecting at time of inspection: Yes/No FRB  
 Required fittings on tubing and casing/tubing annulus: Yes/No/Not Applicable  
 Injection Pressure gas hydrostatic; How Determined when gauge was removed  
 Annular Pressure puff of gas when bullpugging; How Determined was removed  
 Injection Rate 80 Bpd; How Determined Mr. Pope  
 Well plugged at Surface: Yes/No/Undetermined  
 Samples Taken no Photographs Taken 44-05

Description of wellhead hookup and injection facility:  
Active well, tubing has gas hydrostatic head. Annulus had a puff of gas when bullpugging was removed.

Weather Conditions and Observations Clear, south wind at 4 mph, 53°F  
Request sign photo taken from north side, 35 min 5300 MD, 100 ft, ASA 100, 1/25, 93118

Inspection Date 01/03/92 Time Arrived 1335 Departed 1350  
 Field Inspector [Signature]  
 EPA Reviewer [Signature] Date 29 Jan 92